

**AN INVENTORY OF
THE OLD BUILDINGS
OF COLESBERG**

R.H. FITCHETT

AN INVENTORY OF THE OLD BUILDINGS OF COLESBERG.

R.H.FITCHETT.

UNIVERSITY OF THE WITWATERSRAND, JOHANNESBURG. 1989.

CONTENTS.

Introduction.

Inventory.....1

Photographs.....78

Plans.....237

INTRODUCTION.

The inventory is based on a comprehensive survey of the buildings of Colesberg undertaken in 1985, and on a previous photographic survey done in December 1981. The photographs illustrating the inventory were all taken over the period of one week in September 1985. Those dating from 1981 have not been included, but the buildings demolished in the intervening period have been described in the text.

The latest buildings to be described in the inventory date from about the end of the Edwardian period. Without the authority of documentary research, no attempt has been made to assign dates to the individual buildings; however, the dates of proclamation of the erven do provide dates before which the buildings could not have been erected. No attempt has been made to grade the importance of the buildings, apart from descriptions of particularly good examples in the text, as this practice has sometimes had the effect of justifying the demolition of those buildings at the lower end of the scale.

The erven in Colesberg have been re-numbered, so two plans have been included. The first of these (old erf nos.), dating from 1933 and giving the original numbers and dates of proclamation, was provided by a firm of attorneys in Colesberg. The second (new erf nos.), dating from 1973 (a drainage scheme by Louw, Strydom & Partners), was provided by the Colesberg Municipality. The latter has some obvious mis-numberings (eg. Erf 2323, probably Erf 323, but entered in the inventory as received, and Erf 321, which appears twice on the 1973 plan, changed to Erf 327).

The plans illustrating the inventory do not show the major extensions on the northern and south-western sides of Colesberg between 1933 and 1973, as these date from after the period of the buildings under scrutiny. Likewise, with the exception of No. 1 Station Road, the buildings to the north of Chamberlain Square have not been described; although many of the erven shown on the plans date from as early as 1903, the buildings now occupying them consist of modern workshops and warehouses.

The buildings covered in the inventory have been described, where possible, according to the following criteria:-

Erf number (new).
Erf number (old).
Date of proclamation.

Street number and/or building name.
Number of stories, roof configuration and cornice details.
Facade configuration and detailed wall treatment.
Presence of stoep or veranda.
Types of windows.
Types of doors and fanlights.
Condition of building and degree of original appearance retained.

1. Erf 357 (new no.)
Erf 23B (old no.)
Granted 1893.
Vacant.

2. Erven 358 and 359 (new nos.)
Erven 23A and 23 (old nos.)
Granted 1868 and 1834 respectively.

? Stockenström Street.
Modern house.

3. Erven 361 and 362 (new nos.)
Erven 24 and 314 (old nos.)
Granted 1834 and 1906 respectively.
Garden of 40 Stockenström Street.

4. Erven 363 and 364 (new nos.)
Erven (-) and 24A (old nos.)
Granted 1893 and 1894 respectively.

40 Stockenström Street.
Modern house.

5. Erf 365 (new no.)
Erf 25 (old no.)
Granted 1834.

38 Stockenström Street - Photograph, p.78.
Single storey with hipped roof, originally flat.
Symmetrical three bay facade. Pebble dash plaster with smooth door and window surrounds.
Stone stoep with plastered walls. Veranda with concrete Ionic columns.
18-light double sliding sash windows with Venetian shutters.
Modern door.
Good condition, but original appearance lost.

6. Erven 366, 367 and 368 (new nos.)
Erven (-), (-) and (-) (old nos.)
Granted 1864, 1867 and 1880 respectively.

38 Stockenström Street - Photograph, p.78.
Single storey with flat roof and cornice.
Symmetrical three bay facade. Corner pilasters and door and window surrounds.
Stone stoep with plastered walls and corner piers.
8-light double sliding sash windows with Venetian shutters.
Modern door (?) with 2-pane fanlight.
Excellent condition and largely original.

Garage of 38 Stockenström Street - Photograph, p.79.
Flat roofed with loft and light cornice.
Corrugated iron door.
Good condition, original apart from door.

7. Erven 369 and 370 (new nos.)
Erven (-) and (-) (old nos.)
Granted 1868 (both).

34 Stockenstrom Street - Photograph, p.79.
Single storey with hipped roof.
Symmetrical three bay facade. Raked joints and smooth window surrounds.
Stone stoep with plastered walls. Enclosed veranda with concrete columns.
8-light double sliding sash windows. Modern door.
Good condition, but original appearance lost. Lateral additions.

Gateway between 32 and 34 Stockenstrom Street - Photograph, p.80.
Simple brick lintol over entrance in wall linking the two houses.

8. Erven 371, 372 and 373 (new nos.)
Erven 26A, (-B) and (-A) (old nos.)
Granted 1869, 1905 and 1905 respectively.

32 Stockenstrom Street - Photograph, p.80.
Single storey with pitched roof behind stepped parapet.
Straight cornice beneath parapet.
Symmetrical three bay facade, smooth plaster with no door or window surrounds.
Face-brick stoep with no walls. Veranda of face-brick piers.
12-light double sliding sash windows with Venetian shutters.
Modern door.
Good condition, but original appearance affected by brick piers and pitched roof.

Warehouse (garage ?) behind 32 Stockenstrom Street - Photograph, p.81.
Flat roofed with loft and light cornice.
Steel windows.
Good condition, largely original.

9. Erven 375 and 376 (new nos.)
Erven 26 and 26B (old nos.)
Granted 1834 and 1869 respectively.

Gereformeerde Kerk - Photograph, p.81.
Single volume longitudinal church with no aisles or galleries.
Three bay ashlar facade with pilasters, pediment and small belfry.
Stone enclosing wall with cast iron railings.
Round headed windows and arched door.
Excellent condition, original appearance.

10. Erf 379 (new no.)
Erf (-) (old no.)
Granted 1838.

28 Stockenstrom Street
Modern house.

11. Erven 380 and 381 (new nos.)
Erven 27 and AN27 (old nos.)
Granted 1834 and 1899 respectively.

26 Stockenstrom Street - Photograph, p.82.
Single storey with flat roof and cornice.
Asymmetrical four bay facade, no door or window surrounds.
Stone stoep with face-brick piers and steel railings.
Steel windows. Modern door.
Good condition, but original appearance lost apart from cornice.

12. Erven 382 and 383 (new nos.)
Erven AN28 and (-) (old nos.)
Granted 1896 and 1851 respectively.

24 Stockenstrom Street - Photograph, p.82.
Single storey with flat roof and cornice.
Symmetrical three bay facade with window surrounds.
Stone stoep with plastered walls. Veranda on Ionic columns,
ends walled in with windows.
4-light double sliding sash windows with Venetian shutters.
Modern door.
Very good condition, appearance largely original.

13. Erven 384 and 385 (new nos.)
Erven (-A) and 214A (old nos.)
Both granted 1918.
Garden and modern outbuilding of ? Stockenstrom Street.

14. Erven 386 and 387 (new nos.)
Erven (-) and 28 (old nos.)
Granted 1861 and 1834 respectively.

? Stockenstrom Street
Old house, totally modernized - remains of Victorian ventilators.

15. Erf 388 (new no.)
Erf 29 (old no.)
Granted 1838.
Vacant.

16. Erven 398 and 399 (new nos.)
Erven 210A and (-) (old nos.)
Granted 1855 and 1857 respectively.

18 Kort Street - Photograph, p.83.
Single storey with flat roof and cornice.
Symmetrical three bay facade with projecting stoepkamer on left. Raked joints, no door or window surrounds.
Stone stoep with plastered walls and projecting steps.
4-light double sliding sash windows. Original double leaf glazed door.
Excellent condition, largely original.

17. Erf 400 (new no.)
Erf 41 (old no.)
Granted 1838.

14 Kort Street - Photograph, p.83.
Single storey with flat roof and cornice.
Asymmetrical five bay facade.
Face-brick stoep with face-brick piers supporting pergola.
Traces of previous veranda.
12-light double sliding sash windows with Venetian shutters.
Modern door but original decorative fanlight.
Good condition, largely original.

18. Erf 401 (new no.)
Erf (-) (old no.)
Granted 1894.
Vacant.

19. Erf 402 (new no.)
Erf 149 (old no.)
Granted 1882.

10 Kort Street - Photograph, p.84.
Single storey with flat roof and cornice.
Asymmetrical four bay facade with corner pilasters.
Plastered stoep with plastered walls. Veranda on concrete columns.
Steel windows and modern door.
Good condition, but original appearance lost apart from cornice and pilasters.

20. Erf 405 (new no.)
Erven 124, A and B (old nos.)
Granted 1838, 1918 and 1925 respectively.

8 Kort Street - Photograph, p.84.
Single storey with shallow-pitched double pile roof, but no end gables.
Asymmetrical three bay facade with raked joints.
No stoep : veranda with plastered walls and piers, partially enclosed.
Steel windows and modern door.
Fair condition, but original appearance lost.

21. Erf 406 (new no.)
Erf 123 (old no.)
Granted 1838.

6 Kort Street - Photograph, p.85.
Single storey with hipped roof.
Symmetrical three bay facade.
No stoep.
Windows replaced by corrugated iron garage doors. New door, original 8-pane fanlight.
Fair condition, original appearance almost entirely lost.

22. Erf 419 (new no.)
Erf (-) (old no.)
Granted 1838.

4 Kort Street - Photograph, p.86.
Single storey with flat roof and cornice.
Asymmetrical three bay facade with raked joints, smooth door surround and pilasters on corners.
Low stoep with plastered walls and entrance piers. Veranda on plastered piers and enclosed at ends with windows.
Steel windows and modern door.
Good condition, original apart from openings and veranda.

23. Erf 421 (new no.)
Erf (-) (old no.)
Granted 1848.

2 Kort Street - Photograph, p.86.
Single storey with shallow-pitched double pile roof and end gables. Symmetrical three bay facade.
Low stoep with plastered wall. Veranda on plastered piers, enclosed at one end.
Steel windows and modern door.
Good condition, but original appearance lost.

24. Erf 422 (new no.)
Erf 121 (old no.)
Granted 1838.

1 Stockenstrom Square - Photographs, p.87.
Single storey with double pile roof and moulded end gables with false chimneys. Front pitch steeper than back. Symmetrical three bay facade. Low stoep with plastered walls. Verandah on plastered brick piers. Steel windows and modern door. Very good condition. Original apart from openings and veranda.

Garages of 1 and 2 Stockenstrom Square - Photograph, p.88.
Single storey with flat roofs and stepped cornice. Corrugated iron doors. Poor condition, but essential as street edge linkages.

25. Erf 420 (new no.)
Erf 120 (old no.)
Granted 1838.

2 Stockenstrom Square - Photograph, p.88.
Single storey with shallow-pitched double pile roof but no gables. Symmetrical three bay facade. Low stoep with rough slate set into plaster wall. Veranda on plastered piers, partially enclosed in glass. Steel windows and modern door. Good condition, but almost all original appearance lost.

26. Erven 417 and 418 (new nos.)
Erven A and 119 (old nos.)
Granted 1860 and 1862 respectively.

3 Stockenstrom Square - Photograph, p.89.
Single storey with flat roof and cornice with rectangular moulding above latter. Symmetrical three bay facade with edge pilasters. Low stoep with plastered walls. Veranda on plastered piers. 12-light double sliding sash windows. Modern door. Good condition. Original apart from veranda.

27. Erven 415 and 416 (new nos.)
Erven 118 and (-) (old nos.)
Granted 1861 and 1884 respectively.
- 4 Stockenstrom Square - Photograph, p.89.
Single storey with flat roof and decorative parapet, set back from square.
Symmetrical three bay facade.
Veranda on plastered piers.
Double sliding sash windows with Venetian shutters.
Modern door.
Fair condition. Facade obscured by veranda.
28. Erven 413(?), 414(?), 407, 408 and ? (new nos.)
Erven (-), (-), 339, 117 and 340 (old nos.)
Granted 1873, 1873, 1922, 1844 and 1922 respectively.
- Outbuildings of 5 Stockenstrom Square - Photograph, p.90.
Single storey with flat roof and stepped parapet.
Good condition, largely original appearance.
- 5 Stockenstrom Square - Photograph, p.90.
Single storey with cornice, centre gable and hipped roof (revival gable), set back from square.
Asymmetrical five bay facade, rusticated openings.
Stone wall with iron railings on edge of square. Low stoep with plastered walls. Veranda on concrete columns.
12-light double sliding sash windows with Venetian shutters.
Original door.
Very good condition, largely original.
29. Erf 409 (new no.)
Erf 116 (old no.)
Granted 1861.
Garden of 5 Stockenstrom Square.
30. Erf 410 (new no.)
Erf 115 (old no.)
Granted 1862.
- ? Stockenstrom Square.
Modern house.
31. Erven 690 and 793 (new nos.)
Non-existent pre-1930.
No information on date of grant.
Modern police barracks.
32. Erf 444 (new no.)
No Erf number (old no.)
No information on date of grant.
Modern police station.

33. Erf 443 (new no.)
Erf N (old no.)
Granted 1863.

? Stockenstrom Square - Photograph, p.91.
Single storey with flat roof and cornice.
Symmetrical three bay facade.
Low stoep without walls.
Steel windows and modern door.
Good condition, largely original appearance.

Outbuilding.
Single storey with flat roof and light cornice.
Steel windows and doors.
Good condition, largely original appearance.

34. Erf 442 (new no.)
Erf 114 (old no.)
Granted 1838.

? Stockenstrom Square.
Modern house.

35. Erf 441 (new no.)
Erf 113 (old no.)
Granted 1838.

? Stockenstrom Square.
Modern Cape Dutch revival house.

36. Erven 439 and 440 (new nos.)
Annex 12 and Erf 112 (old nos.)
Granted 1920 and 1838 respectively.

12 Stockenstrom Square - Photograph, p.91.
Single storey with double pitched roof and gable. Flat
roofed extension with cornice to the left.
Symmetrical five bay facade (despite irregularity in roof).
Veranda on brick piers.
12-light double sliding sash windows. Modern door.
Good condition. Original appearance apart from veranda.

37. Erf 767 (new no.)
Erven Annex 2 of 38 and (-) (old nos.)
Granted 1920 and 1908 respectively.

13 Stockenstrom Square - Photograph, p.92.
Single storey with hipped roof.
Symmetrical three bay facade.
Plastered stoep with completely enclosed veranda.
Steel windows and modern door to enclosed veranda.
Good condition. Original appearance obscured by additions.

38. Erf 424 (new no.)
Erf 30 (old no.)
Granted 1836.

16 Stockenstrom Street - Photograph, p.92.
Single storey with hipped roof and dormer ventilator.
Symmetrical five bay facade with elaborate door and window surrounds.
Low plastered stoep with precast balustrade. Veranda on precast concrete columns, partially enclosed.
4-light double sliding sash windows with Venetian shutters.
Original door.
Good condition, largely original appearance.

39. Erf 425 (new no.)
Erf 31 (old no.)
Granted 1836.

14 Stockenstrom Street - Photograph, p.93.
Single storey with flat roof and cornice.
Symmetrical three bay facade.
Low plastered stoep with plastered walls. Veranda on precast concrete columns.
12-light double sliding sash windows with Venetian shutters.
Original 6-panel door.
Good condition, largely original appearance.

1 Kort Street - Photograph, p.93.
Single storey with flat roof and cornice.
Symmetrical three bay facade with edge pilasters and door and window surrounds.
No stoep, entrance at pavement level.
Timber casement windows, modern door.
Good condition, largely original appearance.

40. Erf 426 (new no.)
Erf 32 (old no.)
Granted 1836.

12 Stockenstrom Street - Photograph, p.94.
Single storey with double pitched roof and bargeboards.
Cornice suggests original flat roof.
Symmetrical three bay facade with rusticated edges.
Low stoep with veranda on steel V-poles.
Steel windows and modern door.
Good condition but original appearance almost entirely lost.

41. Erf 427 (new no.)
Erf 33 (old no.)
Granted 1836.

10 Stockenstrom Street - Photograph, p.94.
Single storey with double pitched roof. Cornice suggests original flat roof.
Symmetrical five bay facade.
Low stoep with steel railings. Veranda on steel poles.
12-light double sliding sash windows with shutters. Original 6-panel door.
Good condition. Original appearance altered but many details survive.

? Kort Street - Photograph, p.95.
Single storey with flat roof and light cornice.
Steel openings in arbitrary positions.
Largely unoriginal but important as part of street edge.

42. Erf 428 (new no.)
Erf 34 (old no.)
Granted 1836.
Garden of 6 Stockenstrom Street.

43. Erf 429 (new no.)
Erf 35 (old no.)
Granted 1836.

6 Stockenstrom Street - Photograph, p.95.
Single storey with double pitched roof with bargeboards and dormer ventilator.
Asymmetrical five bay facade with raked joints and window surrounds.
No stoep. Projecting portico over door.
Steel windows, modern door.
Good condition, but original appearance affected by loss of details.

44. Erven 430, 431 and 432 (new nos.)
Erven (-), (-) and 36 (old nos.)
Granted 1895, 1842 and 1837 respectively.

4 Stockenstrom Street.
Modern house.

45. Erf 389 (new no.)
Erf H (old no.)
Granted 1862.

Garage of 15 Stockenstrom Street - Photograph, p.96.
Single storey with flat roof and string cornice.
Asymmetrical facade, evidently altered.
Steel door but original lintol.
Good condition. Original appearance largely maintained.

46. Erf 390 (new no.)
Erf I (old no.)
Granted 1862.

15 Stockenstrom Street - Photograph, p.96.
Single storey with hipped roof.
Asymmetrical three bay facade with projecting wing. Raked joints.
Low stoep with plastered walls. Veranda on plastered piers.
One original 4-light double sliding sash window with Venetian shutters.
Good condition. Original appearance largely lost in detail.

47. Erf 391 (new no.)
Erf K (old no.)
Granted 1862.

13 Stockenstrom Street - Photograph, p.97.
Single storey with pitched roof. Bargeboards and finials.
Double pitched stoepkamers, asymmetrical three bay core.
Low stoep with veranda on precast concrete columns.
Steel windows and modern door.
Good condition, but original appearance almost entirely lost.

Garages of 13 and 11 Stockenstrom Street - Photograph, p.97.
Flat roofed with light cornices.
Steel openings.
Original appearance apart from details.

48. Erf 392 (new no.)
Erf L (old no.)
Granted 1862.

11 Stockenstrom Street - Photograph, p.98.
Single storey with flat roof and cornice.
Symmetrical three bay facade with window and door hood mouldings.
Low stoep with pergola on plastered piers.
Steel windows, original door frame and fanlight.
Very good condition, largely original.

49. Erf 393 (new no.)
Erf I (old no.)
Granted 1882.

9 Stockenstrom Street - Photograph, p.98.
Single storey with flat roof and cornice.
Symmetrical three bay facade with rusticated edges and door and window surrounds.
Low stoep, plastered.
12-light double sliding sash windows. Modern door but original fanlight.
Very good condition, almost original appearance.

50. Erf 394 (new no.)
Erf 2 (old no.)
Granted 1882.

7 Stockenstrom Street - Photograph, p.99.
Single storey with flat roof and cornice.
Asymmetrical three bay facade with rusticated edges and door and window surrounds.
Low plastered stoep.
Steel windows and modern door, but original frame and fanlight.
Very good condition, largely original.

51. Erf 395 (new no.)
Erf 3 (old no.)
Granted 1882.

5 Stockenstrom Street.
Completely altered and modernized house.

52. Erf 396 (new no.)
Erf 4 (old no.)
Granted 1882.

3 Stockenstrom Street - Photograph, p.99.
Single storey with hipped roof, flat roof with string cornice over stoepkamer.
Symmetrical three bay facade with edge pilasters and door surround.
Projecting stoepkamer to right.
Low plastered stoep.
4-light double sliding sash windows with Venetian shutters.
Original 6-panel door.
Excellent condition, but over-restored.

53. Erf 397 (new no.)
Erf 5 (old no.)
Granted 1873.

Methodist Church Hall - Photograph, p.100.
Single storey with double pitched roof and bargeboards, with round ventilator in gable.
Symmetrical three bay facade.
Steel windows. Original 6-panel door and fanlight.
Good condition. Appearance affected by windows.

Methodist Church - Photograph, p.100.
Single volume Gothic Revival church with no aisles or galleries. Entrance porch.
Plastered exterior, buttresses between openings.
Plastered enclosing wall with steel railings.
Pointed arched door and windows with hood mouldings.
Excellent condition. Original appearance.

54. Erf 435 (new no.)
Erven 37, (-) and (-) (old nos.)
Granted 1836, 1890 and 1889 respectively.

Magistrate's Court (1890) - Photographs, pp.101 & 102.
Single storey with hipped roofs on wings, double pitched
with parapet gable in centre.
Symmetrical facade of stone.
Veranda on cast iron columns.
Original doors and casement windows.
Excellent condition, almost entirely original appearance.

55. Erf 768 (new no.)
Erven 38 and (-) (old nos. - 38 subsequently subdivided)
Granted 1837 and 1845 respectively.

1 d'Urban Row - Photograph, p.102.
Single storey with hipped roof, lean-to over forward
projection.
Asymmetrical facade with stoepkamer to left.
Low plastered stoep.
12-light double sliding sash window on stoepkamer. Modern
door.
Good condition. Original appearance largely lost, but
important as street edge.

3 d'Urban Row - Photograph, p.103.
Double storey with flat roof, cornice and decorative
parapet.
Symmetrical three bay facade.
Low stoep, plastered. Veranda on plastered piers removed
after 1980.
Lower windows steel, upper 24-light double sliding sash.
Original 6-panel door and Gothic Revival fanlight.
Excellent condition, largely original.

Garage and wall attached to right hand side - Photograph,
p.103.
Flat roofed with light cornice and stepped parapet. Wall
with plaster coping.
Timber door but not original.
Good condition. Largely original and important for street
continuity.

56. Erven 449, 450 and 448 (new nos.)
Erven (-), (-) and (-) (old nos.)
Granted 1895, 1885 and 1896 respectively.

5/7 d'Urban Row - Photographs, p.104.

Single storey with hipped roof. Double pitched roof with decorative fretwork on gable ends of projecting wings. Symmetrical semi-detached houses on stone plinth. Two-bay facades with projecting wings. High stone stoep with fretwork railings. Veranda on plastered pier and timber supports. 24-light double sliding sash windows with Venetian shutters. Original doors. Excellent condition. Original appearance.

57. Erf 451 (new no.)
Erf 39 (old no.)
Granted 1838.

9 d'Urban Row - Photograph, p.105.

Single storey with double pitched roof, bargeboard end gables and timber external staircase to right. Three bay symmetrical facade. Plastered stoep with steel railings. Veranda on plastered piers. 12-light double sliding sash windows with Venetian shutters. Original 8-panel door. Excellent condition. Largely original.

58. Erf 452 (new no.)
Erf (-) (old no.)
Granted 1888.
Garden of 9 d'Urban Row - Photograph, p.105.

59. Erf 453 (new no.)
Erf 40 (old no.)
Granted 1838.

11 d'Urban Row - Photograph, p.106.

Single storey with flat roof and cornice. Asymmetrical four bay facade with edge pilasters and door and window surrounds. Stone stoep with pergola on plastered piers. 12-light double sliding sash windows with Venetian shutters. Modern door. Good condition. Largely original.

60. Erf 782 (new no.)
Erf 111 (old no.)
Granted 1838.

13 d'Urban Row.
Modern house.

61. Erven 783 and 780 (new nos.)
Erven 110 and 109 (old nos.)
Both granted 1844.

15/17 d'Urban Row - Photographs, pp.106 & 107.
Single storey with flat roof and light cornice.
Asymmetrical entrance lobby double pitched with bargeboard gables.

Long facade, each house symmetrical five bay.
Pergola on concrete columns with plastered pedestals.
Steel windows and modern doors.
Good condition, but largely altered appearance.

62. Erf 781 (new no.)
Erf 108 (old no.)
Granted 1851.

19 d'Urban Row.
Modern house.

63. Erf 458 (new no.)
Erf 107 (old no.)
Granted 1882.

21 d'Urban Row - Photograph, p.107.
Single storey with hipped roof.
Symmetrical three bay facade with face-brick edge and rusticated openings.
High stone stoep with plastered walls and projecting staircase. Veranda on plastered piers on three sides.
Timber French doors with Venetian shutters. Modern door.
Good condition, largely original.

64. Erf 459 (new no.)
Erf 106 (old no.)
Granted 1862.

23 d'Urban Row - Photograph, p.108.
Single storey with flat roof and light cornice.
Two bay facade with lateral entrance to projecting room.
Steel windows and modern door.
Good condition but original appearance largely lost.

65. Erf 460 (new no.)
Erf A (old no.)
Granted 1924.

25 d'Urban Row - Photograph, p.108.
Single storey with hipped roof.
Symmetrical three bay facade.
Plastered street wall with steel railings, plastered stoep.
Double curvature veranda on brick piers.
Steel windows but original 4-panel door with arched upper panels.
Good condition, but original appearance largely lost.

66. Erf 462 (new no.)
 Erf 105A (old no.)
 Granted 1904 (erf 105, vacant, granted 1882).
- 27 d'Urban Row - Photograph, p.109.
 Single storey, double pitched roof with bargeboard gabled ends.
 Symmetrical three bay facade.
 Plastered stoep with trellissed railings. Double curvature veranda on timber posts.
 Steel windows, original door.
 Good condition but original appearance largely lost.
67. Erf 463 (new no.)
 Erf 104 (old no.)
 Granted 1849.
- 29 d'Urban Row - Photograph, p.109.
 Single storey with hipped roof.
 Symmetrical three bay facade.
 High plastered stoep with brick wall. Double curvature veranda on brick posts.
 Steel windows, modern door.
 Good condition but original appearance almost entirely lost.
68. Erf 464 (new no.)
 Erf 103 (old no.)
 Granted 1849.
 Demolished house.
69. Erf 465 (new no.)
 Erf 102 (old no.)
 Granted 1849.
- 33 d'Urban Row.
 Modern house.
70. Erf 466 (new no.)
 Erf 101 (old no.)
 Granted 1849.
- 35 d'Urban Row.
 Modern house.
71. Erven 467 and 468 (new nos.)
 Erven 100 and 99 (old nos.)
 Granted 1849 and 1882 respectively.
 Modern warehouse and yard.
72. Erf 469 (new no.)
 Erf 98 (old no.)
 Granted 1882.
- ? d'Urban Row.
 Modern house.

73. Erf 470 (new no.)
Erf 97 (old no.)
Granted 1882.
Garden of ? d`Urban Row.
74. Erf 471 (new no.)
Erf 277 (old no.)
Granted 1910.
Storage yard.
75. Erven 472 and 473 (new nos.)
Erven 276 and 275 (old nos.)
Granted 1910 and 1903 respectively.

? d`Urban Row.
Modern house.
76. Erf 474 (new no.)
Erf 274 (old no.)
Granted 1919.

? d`Urban Row.
Modern house.
77. Erven 476 and 475 (new nos.)
Erven 272 and 273 (old nos.)
Both granted 1903.
Vegetable patch.
78. Erven 478 and 477 (new nos.)
Erven 14 and 15 (old nos.)
Both granted 1883.

? d`Urban Row.
Modern house and garden.
79. Erf 479 (new no.)
Erf 13 (old no.)
Granted 1919.
Modern garage and garden.
80. Erven 480, 481, 482, 483 and 484 (new nos.)
No information and erven 9,8,7 and 6 (old nos.)
Granted (?) and 1884, 1882, 1882 and 1882 respectively.
Colesberg Tennis Club (modern).
81. Erf 485 (new no.)
Erf 5 (old no.)
Granted 1882.

? d`Urban Row.
Modern house.

82. Erf 486 (new no.)
Erf 4 (old no.)
Granted 1882.
Garden.
83. Erf 487 (new no.)
Erf 3 (old no.)
Granted 1864.
- 4 d'Urban Row - Photograph, p.110.
Single storey with hipped roof.
Symmetrical three bay facade with edge pilasters.
No stoep.
Steel windows, modern door.
Good condition but original appearance almost entirely lost.
84. Erven 488 and 489 (new nos.)
Erven 1 and 2 (old nos.)
Both granted 1867.
- ? d'Urban Row, facing away from street - Photographs,
pp.110 & 111.
Single storey with hipped roof and lower double pitched
projecting wings with bargeboard gables.
Symmetrical three bay facade between flanking wings.
Stoep with veranda on plastered piers.
12-light double sliding sash windows with Venetian shutters
on street edge.
Excellent condition, largely original appearance.
85. Erf 616 (new no.)
Erf 311 (old no.)
Granted 1904.
Garden of 51 Church Street.
86. Erf 617 (new no.)
Erf 267 (old no.)
Granted 1899.
Vegetable patch.
87. Erf 618 (new no.)
Erf 268 (old no.)
Granted 1901.
Garden of 1 Venter Street.

88. Erven 619, 620 and 621 (new nos.)
Erven 95, (-) and 94 (old nos.)
Granted 1840, 1868 and 1861 respectively.

1 Venter Street - Photographs, p.112.

Single storey with flat roof and cornice, re-organized to face away from street.

Symmetrical five bay facade.

No stoep remaining, but veranda on face-brick piers and wing walls added to side of house.

Steel windows, door to street removed.

Good condition, and original volume intact, but original appearance lost through alterations.

Garage - Photograph, p.113.

Single storey with shallow double pitched roof and moulded gable.

Non-original doors.

Good condition, largely original appearance.

Outbuilding - Photograph, p.113.

Single storey with flat roof and light cornice.

Modern doors and steel windows, but original lintols intact.

Good condition, largely original appearance.

89. Erven 622 and 623 (new nos.)
Erven 93 and 261 (old nos.)
Granted 1882 and 1897 respectively.
Garden and modern garage.

90. Erf 624 (new no.)
Erf 270 (old no.)
Granted 1903.
Vacant lot.

91. Erf 625 (new no.)
Erf 92 (old no.)
Granted 1882.

? Venter Street - Photographs, pp.113 & 114.

Single storey outbuilding with flat roof and string cornice.

No facade : side wall of building with two doors facing road.

Modern doors but original lintols.

Fair condition, largely original appearance.

92. Erf 626 (new no.)
Erf 91 (old no.)
Granted 1882.
Recently demolished building.

93. Erven 627, 629 and 628 (new nos.)
Erven 221, 220 and Church Ground (old nos.)
Granted 1882, 1882 and 1884 respectively.
- ? Venter Street.
Modern house.
94. Erf 630 (new no.)
Erf 219 (old no.)
Granted 1882.
Modern recreation hall.
95. Erf 631 (new no.)
Erf 218 (old no.)
Granted 1882.
- AGS van SA.
Modern building.
96. Erf 632 (new no.)
Erf 223 (old no.)
Granted 1890.
Orchard.
97. Erven 635 and 634 (new nos.)
Erven 217 and 222 (old nos.)
Granted 1882 and 1890 respectively.
- ? Chamberlain Square - Photograph, p.115.
Single storey with flat roof, cornice lost. Set back from road.
Asymmetrical five bay facade with two doors.
No stoep or veranda. Stone wall framing rear of outbuilding (modern) on Venter Street.
Steel windows and modern door.
Fair condition, but original appearance lost.
98. Erf 633 (new no.)
Erf 252 (old no.)
Granted 1895.
Vacant lot with double garage.
99. Erf 636 (new no.)
Erf 312 (old no.)
Granted 1908.
Vacant lot.
100. Erf 1219 (new no.)
Non-existent before 1930.
Vacant lot.

101. Erf 654 (new no.)
Erf 288 (old no.)
Granted 1903.

1 Station Road - Photographs, pp.115 & 116.
Single storey with hipped roof, and double pitched with bargeboards over rearward extensions.
Symmetrical three bay facade.
No stoep. Double-curvature veranda on 3 sides on remains of timber supports.
Steel windows, modern door.
Dilapidated condition, original appearance largely lost.

102. Erven 597 and 598 (new nos.)
Erven 198 and 213 (old nos.)
Granted 1845 and 1882 respectively.

? Church Street (Fun Centre and Slaghuis) - Photographs, p.117.
Large warehouse, single storey with double pitched roof and later veranda.
Stone wall along Venter Street.
Dilapidated condition, original appearance lost.

103. Erf 599 (new no.)
Erf 214 (old no.)
Granted 1882.
Vacant lot.

104. Erf 600 (new no.)
Erf 215 (old no.)
Granted 1882.
Modern shop.

105. Erf 601 (new no.)
Erf 216 (old no.)
Granted 1882.
Vacant lot.

06. Erven 602 and 603 (new nos.)
Erven 83 and 84 (old nos.)
Granted 1844 and 1882 respectively.

Toorenberg Hotel.
Modern building.

07. Erf 804 (new no.)
 Erf 85 (old no.)
 Granted 1882.

83a Church Street - Photograph, p.118.
 Single storey with hipped roof.
 Asymmetrical four bay facade.
 Arcaded veranda with precast concrete columns, capitals and balustrade above.
 Steel windows, modern door.
 Good condition. Original appearance largely lost, but veranda adds visual interest to street.

Outbuilding on Venter Street - Photograph, p.118.
 Single storey with flat roof and light cornice.
 Side faces street with one modern doorway.
 Good condition, largely original appearance.

108. Erf 805 (new no.)
 Erf 88 (old no.)
 Granted 1882.

82 Church Street.
 Modern shop.

109. Erf 807 (new no.)
 Erf 87 (old no.)
 Granted 1844.

59 Church street.
 Modern shop.

110. Erf 808 (new no.)
 Erf 88 (old no.)
 Granted 1841.

57 Church street - Photograph, p.119.
 Single storey with flat roof and cornice.
 Symmetrical three bay facade with rusticated edges.
 No stoep, plastered walls, veranda on brick piers.
 Steel windows, 4-panel door.
 Good condition, original appearance retained in part.

111. Erf 809 (new no.)
 Erf (-) (old no.)
 Granted 1841.
 Vacant.

12. Erven 610, 611 and 612 (new nos.)
Erven (-), (-) and (-) (old nos.)
Granted 1867, 1867 and 1839 respectively.

? Church Street - Photograph, p.119.
Single storey with flat roof and cornice.
Symmetrical three bay facade with rusticated right hand edge.
No stoep or veranda.
Steel windows, modern door.
Fair condition, original appearance retained in part.

113. Erf 613 (new no.)
Erf 89 (old no.)
Granted 1839.

? Church Street - Photograph, p.120.
Modernized shop.

Garage behind, facing Erf 614 - Photograph, p.120.
Flat roofed with light cornice.
Dilapidated condition but largely original.

114. Erven 614 and 615 (new nos.)
Erven (-) and 90 (old nos.)
Granted 1840 and 1839 respectively.

51 Church Street.
Modern house.

115. Erf 504 (new no.)
Erf 200 (old no.)
Granted 1845.

2, New Street - Photographs, pp.121 & 122.
Single storey with flat roof and cornice.
Symmetrical three bay facade.
Low plastered stoep.
Windows blocked up, modern 4-panel door.
Dilapidated condition. Maintains original appearance despite loss of windows.

1 New Street - Photographs, pp.121 & 122.
Single storey with flat roof and cornice.
Two bay facade with door and window surrounds and pilaster on Church Street corner.
Low plastered stoep.
Door and windows blocked up.
Dilapidated condition. Maintains original appearance despite loss of windows.

This pair of buildings would be a valuable asset to Colesberg if correctly restored.

116. Erf 503 (new no.)
Erf A (old no.)
Granted 1929.

49 Church Street - Photograph, p.122.
Asymmetrical villa : hipped roof with double pitched roof over projection and vestigial turret on right hand corner. Asymmetrical facade with bay window under turret. No stoep but plastered wall. Veranda on brick piers. Steel window in projecting wing. 4-light double sliding sash windows elsewhere. Original 6-panel door. Good condition. Retains original appearance apart from alterations to projecting wing.

117. Erf 502 (new no.)
Erf 203 (old no.)
Granted 1856.

? Church Street ("Ellerslie") - Photograph, p.123.
Single storey with flat roof and heavy cornice. Symmetrical three bay facade. No stoep but plastered wall. Veranda on plastered piers. 24-light double sliding sash windows. 4-panel door with coloured glass fanlight. Very good condition. Original appearance largely retained.

118. Erven 501, 500 and 499 (new nos.)
Erven 204, 205 and 206 (old nos.)
Granted 1861, 1856 and 1847 respectively.
Nursery.

119. Erf 498 (new no.)
Erf 207 (old no.)
Granted 1846.

39 Church Street - Photograph, p.123.
Single storey with shallow double pitched roof and bargeboard ends. Asymmetrical five bay facade (left window replaced by door), with raked joints. No stoep but plastered wall. Double curvature veranda on brick piers. 4-light double sliding arch-headed sash windows with Venetian shutters. Original 6-panel front door. Good condition. Facade largely original.

120. Erf 497 (new no.)
Erf 208 (old no.)
Granted 1847.
Modern block of flats.

1. Erf 496 (new no.)
Erf 209 (old no.)
Granted 1846.

35 Church Street - Photograph, p.124.
Single storey with hipped roof.
Asymmetrical four bay facade with raked joints.
No stoep but plastered wall with buttresses and decorative panels. Veranda on plastered piers.
4-light double sliding sash windows with Venetian shutters.
Modern door.
Good condition. Largely original appearance.

22. Erf 494 (new no.)
Erf 210 (old no.)
Granted 1846.

33a Church Street.
Modern office.

23. Erven 493 and 492 (new nos.)
Erven (-) and 211 (old nos.)
Granted 1885 and 1846 respectively.

? Church Street - Photograph, p.124.
Single storey with flat roof and heavy cornice.
Asymmetrical five bay facade.
No stoep or veranda.
Steel windows and doors of arbitrary sizes.
Good condition, but original appearance lost apart from cornice.

124. Erf 491 (new no.)
Erf 212 (old no.)
Granted 1846.

27 Church Street - Photographs, p.125.
Single storey with flat roof and heavy cornice.
Asymmetrical five bay facade (right hand window now garage door) with edge pilasters and door and window surrounds.
No stoep but plastered curved walls. Veranda on brick piers.
24-light double sliding sash windows. Original 6-panel door and fanlight.
Excellent condition. Largely original.

25. Erf 490 (new no.)
Erf 213 (old no.)
Granted 1849.

Christ Church (Anglican) - Photographs, p.126.
Entrance portico, nave and chancel, with no aisles. Steeply pitched roof.
Plastered exterior, corner buttresses.
Plastered enclosing wall with iron railings.
Pointed arched doors and windows with smooth plaster surrounds.
Excellent condition. Original appearance.

126. Erven 545 and 544 (new nos.)
Erven 147 and 148 (old nos.)
Both granted 1845.
Modern supermarket.

127. Erven 540 and 539 (new nos.)
Erven 149 and (-) (old nos.)
Granted 1844 and 1847 respectively.

? Church Street - Photograph, p.127.
Single storey with hipped roof screened with precast balustrade, entrance on right hand side.
Asymmetrical street facade behind veranda.
Arcaded veranda with precast columns and capitals, precast balustrades between. Veranda partially enclosed by precast wall.
Steel windows, no door on street facade.
Good condition, but largely unoriginal appearance.

128. Erf 538 (new no.)
Erf 150 (old no.)
Granted 1846.

40/40a Church Street - Photograph, p.127.
Single storey with hipped roof.
Asymmetrical six bay facade with rusticated edges and raked joints.
No stoep, modern overhang.
One remaining timber casement window, otherwise modern shopfronts and modern doors.
Good condition, but original appearance lost.

129. Erf 535 (new no.)
Erf 151 (old no.)
Granted 1846.
Garden of 40/40a Church Street.